HOW TO LOAD WINDOWS 7 USB DRIVER FOR TS9000, TS9000A, TS9050 and TS9080

Date: 01/06/11

The TS9000, TS9000A, TS9050 and TS9080 were not designed for Windows7, since Windows7 does not allow loading driver directly from disk. But there is a work-around.

1. Download *CDM 2.04.16 WHQL Certified E470* usb driver

2. Extract-All to your desktop

3. Connect the TS90xx analyser to USB port

Click the following:

4. Start
5. Control Panel
6. Hardware and Sound
7. Device Manager
8. Other Devices
9. TS90xx FM Analyser
10. Right click and select Update Driver Software (if this does not show, you may have to re-boot your PC now)
11. Browse my computer for driver software
12. click Browse and select usb CDM 2.04.16 WHQL Certified E470 folder on your desktop

Windows should then load the correct driver.